

1/7




Fig. 1

2/7




Fig. 2

3/7




Fig. 3

4/7




Fig. 4




Fig. 5

6/7




Fig. 6

7/7

Slave mixer

$q_1 = 2 \quad n_1 = 2$

$q_2 = 5 \quad n_2 = 1$

$q_3 = 4 \quad n_3 = 5$

$q_4 = 10 \quad n_4 = 2$

Master mixer

$s_1 = 2 \quad i_1 = 1$

$s_2 = 4 \quad i_2 = 4$

$s_3 = 5 \quad i_5 = 7$

9	8	7	6	5	4	3	2
8	7	6	5	4	3	2	1
12	11	10	9	8	7	6	5
9	8	7	6	5	4	3	2

Fig. 7